

Gauge Installation:


1. Select the desired mounting location of the instrument.
2. Mount the gauge and secure with the VDO Clamp.

Wiring the Gauge (Illustration A):

1. Route wires from the instrument to:
 - (a) the light switch after the fuse box or user supplied in-line fuse - 1 amp.
 - (b) a good, dedicated ground location.

Gauge hookup:

Wiring Diagram	
S	Sender wire connection (This is the ground connection for Voltmeter application)
GND	Ground (-)
I (POS)	Positive (+ 12V)



Read these instructions thoroughly before installation. Do not deviate from assembly or wiring diagram. Always disconnect battery ground before making any electrical connections.

IMPORTANT: Mounting dimensions vary for different gauges. Please be certain to follow the instructions for your specific gauge.